

REPORT OF CHANNEL CONDITIONS
(FOR CHANNELS 400 FEET WIDE OR GREATER)
(ER 1130-2-316)

TO:
Port Director, Tampa Port Authority
P.O. Box 2192, Tampa, FL

FROM
USACE, District Engineer
Attn: CESAJ-CO-OM Jacksonville, Florida

RIVER/HARBOR NAME AND STATE
Tampa Harbor, Hillsborough Co., FL

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	Date of Survey	AUTHORIZED PROJECT			Left Outside Quarter (feet)	Left Inside Quarter (feet)	Right Inside Quarter (feet)	Right Outside Quarter (feet)
		Width (feet)	Length (miles)	Depth (feet)				
Entrance Channels: Egmont Cut-1; From Buoy-2 to Buoy-15	Jun-2011	700-1000	12.7	45	44.1	46.8	47.1	46.1
Egmont Cut-2 and Widener; From Buoy-15 to Buoy-20	May-2011	700-1000	2.5	43	40.7	45.4	48.4	45.1
Mullet Key Cut and Widener; From Egmont Buoy-20 to Buoy-26	Jan-2011	600-900	4.2	43	42.0	42.8	43.2	40.8
Cut-A & Widener; From Buoy-26 to Buoy-6A	Jul-2011	500-700	3.2	43	43.0	43.7	43.2	42.9
Cut-B and Widener; From Buoy-6A to Buoy-1C	Jul-2011	500-700	4	43	42.4	41.8	42.2	42.3
Cut-C and Widener; From Buoy-1C to Buoy-6C	Jun-2011	500-750	2	43	42.6	42.9	43.5	43.2
Entrance Channels Cut-D and Widener; From Buoy-6C to Buoy- 6D	May-2011	500-650	2.5	43	43.7	41.6	42.4	41.8
Cut-E and Widener; From Buoy-6D to Buoy-6E	Apr-2011	500-700	2.4	43	42.7	43.4	42.2	42.4
Cut-F; From Buoy-6E to 1200 feet west of Buoy-10F	Mar-2011	500	1.8	43	43.5	43.5	44.1	42.5
Port Tampa Channel: Cut-G; From Buoy-1G to 2100 feet west of Buoy- 7G & Widener	May-2011	400	3.1	34	34.0	35.0	34.8	34.8
Cut - F / Cut - G Widener From Buoy 7F to Buoy 1G	May-2011				33.5	36.0	38.4	39.4
Cut-J and Widener; From 1050 feet southwest of Buoy-10J up to Buoy- 13J	Aug-2011	400-450	1.3	34	32.3	35.2	34.2	34.4
Cut - G to Cut - J Widener From Buoy 8G to Buoy 12J	Aug-2011				35.4	36.7	38.9	34.0
Cut-J2 and Widener to Cut-K; From Buoy-13J to Buoy-6K	Aug-2011	400-450	2.6	34	31.9	36.6	36.9	34.4
Cut-K; From Buoy-6K to Buoy-9K	Aug-2011	400	0.8	34	34.7	36.5	33.2	33.5

TO: Port Director, Tampa Port Authority P.O. Box 2192, Tampa, FL	FROM USACE, District Engineer Attn: CESAJ-CO-OM Jacksonville, Florida
---	--

RIVER/HARBOR NAME AND STATE Tampa Harbor, Hillsborough Co., FL	MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD
--	--

NAME OF CHANNEL	Date of Survey	AUTHORIZED PROJECT			Left Outside Quarter (feet)	Left Inside Quarter (feet)	Right Inside Quarter (feet)	Right Outside Quarter (feet)
		Width (feet)	Length (miles)	Depth (feet)				

Remarks:

Survey #11-031 Entrance Channel, Egmont and Mullet Key
 #11-036 Cut-A, B, C, D, E
 #11-073 Cut - E
 #11-037 Cut - F, G, J, J-2, K and Wideners