

**REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 400 FEET WIDE OR GREATER**  
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: March 10, 2014

TO:  
Port Director, Tampa Port Authority  
P.O. Box 2192, Tampa, Florida

FROM:  
USACE, District Engineer  
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE  
Tampa Harbor, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD			
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)	LEFT QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT QUARTER (feet)
Cut-A (TB) Sta. 0+00 to 166+61.07	Feb-14	500	3.2	43	41.5	42.8	42.5	42.5
Cut-B (TB) Sta. 0+00 to 209+55.47	Feb-14	500	4.0	43	41.8	41.6	42.3	41.5
Cut-C (TB) Sta. 0+00 to 105+12.12	Feb-14	500	2.0	43	41.9	41.7	42.4	42.5
Cut-D (TB) Sta. 0+00 to 131+53.95	Apr-13	500	2.5	43	42.6	41.4	41.9	41.2
Cut-E (TB) Sta. 0+00 to 125+04.66	Mar-13	500	2.4	43	41.2	42.0	42.3	42.1

REMARKS(Continue on reverse )  
**Survey #12-217**