

**REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 400 FEET WIDE OR GREATER**

(ER 1130-2-316)

PAGE: 1 of 1

DATE: 1-Jan-13

TO: CESAJ-OD Brian Brodehl

FROM: CESAJ-OD Deb Williams
Lisa Holland

THRU: CESAJ-OD Dale Traylor

RIVER/HARBOR NAME AND STATE

Jacksonville Harbor, FL

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER	LEFT INSIDE QUARTER	RIGHT INSIDE QUARTER	RIGHT OUTSIDE QUARTER
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>	<i>(feet)</i>	<i>(feet)</i>	<i>(feet)</i>	<i>(feet)</i>
Terminal Channel: from beginning of Terminal Channel to 500 feet south of green light Buoy-75	Oct-12	575-1340	1.2	40	34.5	37.4	38.9	37.8

REMARKS *(Continue on reverse)*

Survey #13-003 - Sta. 26+00 to 67+00, Dated October 2012

|

|

|

|

|

|