

REPORT OF CHANNEL CONDITIONS FOR CHANNELS 200 FEET WIDE OR GREATER <i>(ER 1130-2-316)</i>						PAGE: 1 of 1		
TO: Port Director, Tampa Port Authority P.O. Box 1292, Tampa , Florida						FROM: USACE, District Engineer Attn: CESAJ-OD-H Jacksonville, Florida		
RIVER/HARBOR NAME AND STATE Big Bend Channel, Tampa Harbor, Hillsborough County, Florida						MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	LEFT INSIDE QUARTER <i>(feet)</i>	RIGHT INSIDE QUARTER <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>				
Entrance Channel Sta. 0+00 to 115+80.68	Jan-14	200	2.19	35	31.6	35.7	35.4	31.9
Agrico Berthing Area Sta. 115+80.68 to 136+88.97	Jan-14	300	0.40	35	35.1	34.2	33.9	32.6
Inner Channel Cut-1 Sta. 0+00 to 29+20.71	Jan-14	200	0.55	35	31.3	35.8	33.4	30.1
Inner Channel Cut-2 Sta. 29+20.71 to 44+08.77	Jan-14	200	0.28	35	30.1	33.1	30.2	31.6
Cut-A (HB) Sta. 40+00 to 60+44.90	Jan-14	500	0.39	43	43.6	43.0	43.2	40.7
Cut-C (HB) Sta. 0+00 to 20+00	Jan-14	500	0.38	43	43.6	43.5	42.6	42.9
Cut-A (HB) Widener Sta. 31+10 to 60+44.90	Jan-14	Varies	0.56	43	42.7	44.7	44.4	44.3
Cut-C (HB) Widener Sta. 0+00 to 29+35	Jan-14	Varies	0.56	43	39.8	41.1	43.5	43.5
Entrance Channel Widener	Jan-14	Varies	Varies	35	35.5			
Entrance Channe Turning Basin North	Jan-14	Varies	0.26	35	13.0			
Entrance Channe Turning Basin South	Jan-14	Varies	0.26	35	23.3			
REMARKS(Continue on reverse) Survey #14-029								