

**REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 400 FEET WIDE OR GREATER**  
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: March 26, 2014

TO:  
Port Director, Tampa Port Authority  
P.O. Box 2192, Tampa, Florida

FROM:  
USACE, District Engineer  
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE  
Tampa Harbor, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT	LEFT	RIGHT	RIGHT
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)	OUTSIDE QUARTER (feet)	INSIDE QUARTER (feet)	INSIDE QUARTER (feet)	OUTSIDE QUARTER (feet)
Cut-J1 Sta. 0+00 - 67+00.02	Mar-14	400	1.3	34	32.4	34.8	34.0	33.7
Cut-J1 Widener	Mar-14	Varies		34	32.6			
Cut-J2 Sta. 0+00 - 58+87.86	Mar-14	400	1.1	34	35.5	37.0	36.7	35.6
Cut-K Sta. 0+00 - 150+00	Mar-14	400	2.8	34	30.7	32.5	35.3	32.0
Cut-K Widener Sta. 120+00 - 150+00	Mar-14	Varies	0.6	34	30.5			

REMARKS(Continue on reverse)  
**Survey 14-066**