

REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 400 FEET WIDE OR GREATER  
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: March 26, 2015

TO:  
Port Director, Tampa Port Authority  
P.O. Box 2192, Tampa, Florida

FROM:  
USACE, District Engineer  
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE  
Tampa Harbor, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Mullet Key Sta. 0+00 to 219+99.98	Mar-15	600	4.2	43	41.6	42.9	42.9	40.6
Cut-A (TB) Sta. 0+00 to 166+61.08	Feb-15	500	3.2	43	40.3	42.2	42.4	42.6
Cut-B (TB) Sta. 0+00 to 209+55.47	Mar-15	500	4.0	43	41.6	41.4	42.1	40.9

REMARKS(Continue on reverse)

Survey #14-170