

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 400 FEET WIDE OR GREATER
(ER 1130-2-316)

PAGE: 1 of 1

DATE: November 3, 2014

TO:
Executive Director, Ports Authority Commonwealth of Puerto Rico
San Juan, Puerto Rico

FROM:
USACE, District Engineer
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE

Arecibo Harbor, Puerto Rico

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Reach 2 Sta 18+00.01 to Sta 20+00	10/26/14	650	0.04	25	26.5	25.7	25.9	25.3
Reach 1 Sta 2+00 to Sta 18+00.01	10/26/14	400	0.30	25	18.2	22.8	17.4	8.0
Reach 1 South Basin Sta 2+00 to Sta 10+00	10/26/14	Varies	0.15	25	5.8	5.3	4.9	4.6
Reach 1 North Pier Sta 2+00 to Sta 9+52.18	10/26/14	Varies	0.14	25	15.2			

REMARKS(Continue on reverse)

Survey # 15-006