

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(EP 1130-2-520)

PAGE: 1 OF 1

DATE: 25-Jun-15

TO:
 Chairman, Board of County Commissioners
 Sarasota, Fl.

FROM:
 USACE, District Engineer
 Attn: CESAJ-OD-H Jacksonville, Florida

New Pass, Sarasota County, Florida

MINIMUM DEPTHS IN CHANNEL
 ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	MIDDLE HALF <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>			
Cut-1 Sta. 0+00 to 28+33.68	Jun-15	150	0.54	10	4.1	4.0	5.1
Cut-2 Sta. 0+00 to Sta. 16+46.96	Jun-15	150-125	0.31	10	7.1	5.9	4.8
Cut-3 Sta. 0+00 to Sta. 16+90.58	Jun-15	125-100	0.32	8	8.7	9.8	10.1
Cut-4 Sta. 0+00 to Cut 7 Sta. 19+96.81	Jun-15	100	0.38	8	5.5	8.1	8.9
Cut-5 Sta. 0+00 to Sta.23+42.07	Jun-15	100	0.44	8	8.8	8.1	8.0
Cut-6 Sta. 0+00 to Sta. 39+30.60	Jun-15	100	0.74	8	4.2	4.2	4.3
Cut-7 Sta. 0+00 to Sta. 35+21.93	Jun-15	100	0.67	8	8.5	9.1	9.3
Turning Basin: Sta. 0+00 to Sta. 8+00	Jun-15	Varies	0.15	8	7.3	5.1	3.5

REMARKS *(Continue on reverse)*

Survey #15-121