

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 400 FEET WIDE OR GREATER
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: May 10, 2016

TO:
Port Director, Tampa Port Authority
P.O. Box 2192, Tampa, Florida

FROM:
USACE, District Engineer
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE
Tampa Harbor, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Mullet Key Sta. 0+00 to 219+99.98	Apr-16	600	4.2	43	42.3	43.2	43.3	38.5
Cut-A (TB) Sta. 0+00 to 166+61.08	Apr-16	500	3.2	43	42.0	42.4	42.9	42.2
Cut-B (TB) Sta. 0+00 to 209+55.47	Feb-16	500	4.0	43	41.5	42.8	42.6	40.8

REMARKS (Continue on reverse)
Survey #16-089