

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 400 FEET WIDE OR GREATER
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: 20-Mar-2017

TO:
Port Director, Tampa Port Authority
P.O. Box 2192, Tampa, Florida

FROM:
USACE, District Engineer
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE
Tampa Harbor, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT	LEFT	RIGHT	RIGHT
		WIDTH	LENGTH	DEPTH	OUTSIDE QUARTER	INSIDE QUARTER	INSIDE QUARTER	OUTSIDE QUARTER
		(feet)	(miles)	(feet)	(feet)	(feet)	(feet)	(feet)
Egmont Bar Cut-1 Sta. 00+00 - 274+00	Feb-17	700	5.19	45	43.6	47.3	47.6	45.99
Egmont Bar Cut-1 Sta. 274+00 - 390+00	Feb-17	700	2.19	45	42.0	46.8	47.6	43.83
Egmont Bar Cut-1 Sta. 390+00 - 670+17.30	Feb-17	700	5.3	45	36.71	44.55	45.08	41.31
Egmont Bar Cut-2 Sta. 0+00 - 132+90.06	Feb-17	700	2.52	45	43.7	45.4	47.7	43.08

REMARKS(Continue on reverse)
Survey 16-169