REPORT OF CHANNEL CONDITIONS FOR CHANNELS 400 FEET WIDE OR GREATER

(ER 1130-2-316)

PAGE:

1 of 1

DATE:

October 12, 2016

TO: FROM:

Manatee County Port Authority

13231 Eastern Avenue, Palmetto, Florida

USACE, District Engineer Attn: CESAJ-OD-H Jacksonville, Florida

Manatee Harbor, Manatee County, Florida

RIVER/HARBOR NAME AND STATE MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD LEFT **LEFT RIGHT RIGHT** DATE **AUTHORIZED PROJECT** OUTSIDE **INSIDE INSIDE** OUTSIDE NAME OF CHANNEL OF **WIDTH** LENGTH DEPTH QUARTER QUARTER QUARTER QUARTER **SURVEY** (feet) (miles) (feet) (feet) (feet) (feet) (feet) Entrance Channel Sep-16 1056-600 0.42 40 38.9 40.2 39.6 38.8 Sta. 171+29.18 to 149+15.99 North Widener 40 37.2 Varies Varies South Widener Varies Varies 40 40.8 40.4 39.4 37.3 **Entrance Channel** Sep-16 600 0.41 40 39.8 40.0 39.9 39.9 Sta. 149+15.99 to 127+42.00 **Entrance Channel** Sep-16 600-400 0.65 40 40.2 40.2 40.0 40.2 Sta. 127+42.00 to 93+28.11 Entrance Channel Sep-16 400 1.36 40 35.1 39.6 39.9 37.4 Sta. 93+28.11 to 21+38.32 Entrance Channel Sep-16 400-426 0.10 40 39.7 41.0 42.5 40.8 Sta. 21+38.32 to 16+13.22 North Widener Varies Varies 40 40.5 South Widener Varies Varies 40 38.5 Federal Turning Basin Sep-16 Varies 0.25 40 38.6 39.0 37.0 37.6

0.13

Varies

Varies

40

40

40

27.0

32.1

34.5

37.7

40.3

37.1

36.1

40.0

38.6

31.6

39.3

38.3

Varies

Varies

Varies

Sep-16

Sep-16

Sep-16

REMARKS(Continue on reverse)

Sta. 32+81.08 to 19+56.38

Survey # 16-171

East Berthing

South 1 Berthing

South 2 Berthing

ENG 4020-R, NOV 90 (VI)