

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 100 FEET WIDE OR GREATER
(ER 1130-2-316)

November 17, 2016

TO: City Manager, City of Tarpon Springs 101 South Pinellas Avenue, Tarpon Springs, Florida	FROM: USACE, District Engineer Attn: CESAJ-ODH Jacksonville, Florida
---	--

RIVER/HARBOR NAME AND STATE Anclote River, Tarpon Springs, Florida	MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD			
	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:33%;">LEFT</td> <td style="width:33%;">CENTER</td> <td style="width:33%;">RIGHT</td> </tr> </table>	LEFT	CENTER	RIGHT
LEFT	CENTER	RIGHT		

CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			OUTSIDE QUARTER (feet)	HALF (feet)	OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Cut - 1 Sta. 00+00 - 52+80	Sep-16	100	1.00	9	8.3	8.0	8.0
Cut - 1 Sta. 52+80 - 72+60.31	Sep-16	100	0.38	9	8.3	9.7	9.7
Cut - 2 Sta. 00+00 - 52+80	Sep-16	100	1.00	9	6.4	6.9	7.7
Cut - 2 Sta. 52+80 - 105+60	Sep-16	100	1.00	9	3.5	2.3	3.2
Cut - 2 Sta. 105+60 - 146+45.76	Sep-16	100	0.77	9	9.6	9.5	9.3
Cut - 3 Sta. 00+00 - 70+20.39	Nov-16	100	1.33	9	8.2	8.6	8.2
Cut - 3A Sta. 00+00 - 5+69.45	Nov-16	100	0.11	9	10.1	10.3	9.9
Cut - 4 Sta. 00+00 - 39+97.01	Nov-16	100	0.76	9	8.1	8.5	8.9
Cut - 5 Sta. 00+00 - 34+60.08	Nov-16	100	0.66	9	6.8	7.0	7.7
Cut - 6 Sta. 00+00 - 18+93.46	Nov-16	100	0.66	9	7.8	9.6	7.6
Cut - 7 Sta. 00+00 - 26+51.54	Nov-16	100	0.66	9	6.7	9.0	7.2
Cut - 8 Sta. 00+00 - 13+07.44	Nov-16	100	0.66	9	10.1	10.0	8.8
Cut - 9 Sta. 00+00 - 9+60.13	Nov-16	100	0.66	9	9.1	9.2	8.0
Cut - 10 Sta. 00+00 - 5+60.18	Nov-16	100	0.66	9	9.3	10.2	9.0
Cut - 11 Sta. 00+00 - 6+36.37	Nov-16	100	0.66	9	8.0	10.0	8.9
Cut - 12 Sta. 00+00 - 13+55.33	Nov-16	100	0.66	9	8.1	9.3	8.1
Cut - 13 Sta. 00+00 - 4+65.00	Nov-16	100	0.08	9	9.9	9.8	8.3
Cut - 14 Sta. 00+00 - 4+00.00	Nov-16	100	0.08	9	8.6	10.0	8.4
Turning Basin	Sep-16	Varies	0.18	9	2.2	2.0	7.5

REMARKS(Continue on reverse)
Survey 17-029

