

<b>TO:</b> Chief, Coastal Management Div., Board of Co. Commisioners 440 Court Street, Clearwater, FL	<b>FROM</b> USACE, District Engineer Attn: CESAJ-CO-OM Jacksonville, Florida
---	--

<b>RIVER/HARBOR NAME AND STATE</b> Johns Pass, Pinellas Co., FL	<b>MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD</b>
--	--

NAME OF CHANNEL	Date of Survey	AUTHORIZED PROJECT			Left Outside Quarter (feet)	Middle Half (feet)	Right Outside Quarter (feet)
		Width (feet)	Length (miles)	Depth (feet)			
Entrance Channel: Cut-1, from 300 feet landward of red light-2 to red light-4	Apr-2004	150	0.4	10	8.0	12.5	13.5
Cut-2 & 2A, from red light-4 to the State Road 699 Bridge	Apr-2004	150	0.4	10	11.1	13.5	12.6
Cut-2C thru Cut-4, from the State Road 699 Bridge to 550 feet north of green light-7	Apr-2004	100	0.8	8	12.8	7.9	7.1
Cut-5 thru Cut-7, from 550 feet north of green light-7 to the intersection of the Intracoastal Waterway	Apr-2004	100-600	0.7	6	4.8	5.5	6.4

**Remarks:**

- (1) Minor shoaling along the eastern edge of widener of Cut-4/5.
  
- (2) Minor shoaling in northern half of channel from 800 feet south of and extending to red light-10.