

REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 50 FEET WIDE OR GREATER  
(ER 1130-2-316)

PAGE: 1 of 3  
DATE: March 6, 2015

TO: County Manager  
3301 East Tamiami Trail Administration Building, Naples, Florida

FROM: USACE, District Engineer  
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE					MINIMUM DEPTHS IN EACH 1/3 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
Everglades Harbor, Collier County, Florida					LEFT OUTSIDE	CENTER INSIDE	RIGHT OUTSIDE
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			(feet)	(feet)	(feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Cut-7 Sta. 0+00 - Sta. 48+32.15	Feb-15	60	0.92	8	4.7	4.3	3.6
Cut-8 Sta. 0+00 - Sta. 52+80	Feb-15	60	1	8	3.9	5.1	4.1
Cut-8 Sta. 52+80.00 - Sta. 87+20.17	Feb-15	60	0.65	8	4.5	4.4	3.8
Cut-9 Sta. 0+00 - Sta. 9+86.57	Feb-15	60	0.19	8	6.7	6.0	4.5
Cut-10 Sta. 0+00 - Sta. 2+02.49	Feb-15	60	0.04	8	8.7	8.9	8.4
Cut-11 Sta. 0+00 - Sta. 2+15.41	Feb-15	60	0.04	8	7.8	8.9	8.6
Cut-12 Sta. 0+00 - Sta. 1+91.05	Feb-15	60	0.04	8	7.0	7.6	7.1
Cut-13 Sta. 0+00 - Sta. 7+84.48	Feb-15	60	0.15	8	5.3	6.2	6.0
Cut-14 Sta. 0+00 - Sta. 4+23.70	Feb-15	60	0.08	8	3.4	4.4	5.3
Cut-15 Sta. 0+00 - Sta. 2+19.00	Feb-15	60	0.04	8	3.4	4.7	6.2
Cut-16 Sta. 0+00 - Sta. 4+15.96	Feb-15	60	0.08	8	4.1	5.2	4.8

REMARKS(Continue on reverse)  
Survey 15-030

REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 50 FEET WIDE OR GREATER  
(ER 1130-2-316)

PAGE: 2 of 3

DATE: March 6, 2015

TO:  
County Manager  
3301 East Tamiami Trail Administration Building, Naples, Florida

FROM:  
USACE, District Engineer  
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE					MINIMUM DEPTHS IN EACH 1/3 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
Everglades Harbor, Collier County, Florida							
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE (feet)	CENTER INSIDE (feet)	RIGHT OUTSIDE (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Cut-17 Sta. 0+00 - Sta. 14+90.04	Feb-15	60	0.28	8	5.8	6.1	6.1
Cut-18 Sta. 0+00 - Sta. 5+26.31	Feb-15	60	0.10	8	7.3	7.3	7.2
Cut-19 Sta. 0+00 - Sta. 4+52.77	Feb-15	60	0.09	8	6.8	5.6	4.6
Cut-20 Sta. 0+00 - Sta. 7+44.32	Feb-15	60	0.14	8	6.5	6.7	6.1
Cut-21 Sta. 0+00 - Sta. 5+36.66	Feb-15	60	0.10	8	7.0	7.0	7.7
Cut-22 Sta. 0+00 - Sta. 6+60.00	Feb-15	60	0.13	8	4.5	4.0	6.4
Cut-N-1 Sta. 0+00 - Sta. 1+92.94	Feb-15	60	0.04	8	7.0	7.6	7.1
Cut-N-2 Sta. 0+00 - Sta. 4+10.17	Feb-15	60	0.08	8	5.3	6.2	6.0
Cut-N-3 Sta. 0+00 - Sta. 3+16.75	Feb-15	60	0.06	8	3.4	4.4	5.3
Cut-N-4 Sta. 0+00 - Sta. 3+07.34	Feb-15	60	0.06	8	3.4	4.7	6.2

REMARKS(Continue on reverse)  
Survey 15-030

REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 50 FEET WIDE OR GREATER  
(ER 1130-2-316)

PAGE: 3 of 3

DATE: March 6, 2015

TO:  
County Manager  
3301 East Tamiami Trail Administration Building, Naples, Florida

FROM:  
USACE, District Engineer  
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE					MINIMUM DEPTHS IN EACH 1/3 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
Everglades Harbor, Collier County, Florida					LEFT	CENTER	RIGHT
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE (feet)	CENTER INSIDE (feet)	RIGHT OUTSIDE (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Cut-S-1 Sta. 0+00 - Sta. 49+04.56	Feb-15	60	0.93	8	7.3	6.6	6.6
Cut-S-2 Sta. 0+00 - Sta. 52+80	Feb-15	60	1	8	6.8	6.8	6.8
Cut-S-2 Sta. 52+80.00 - Sta. 92+83.29	Feb-15	60	0.76	8	8.7	9.5	9.4
Cut-S-3 Sta. 0+00 - Sta. 41+51.37	Feb-15	60	0.79	8	1.8	1.8	1.9
Cut-S-4 Sta. 0+00 - Sta. 22+80.28	Feb-15	60	0.43	8	1.9	5.6	6.6

REMARKS(Continue on reverse)  
Survey 15-030