

REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 400 FEET WIDE OR GREATER  
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: May 11, 2016

TO:  
Port Director, Tampa Port Authority  
P.O. Box 2192, Tampa, Florida

FROM:  
USACE, District Engineer  
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE  
Tampa Harbor, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT	LEFT	RIGHT	RIGHT
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>	OUTSIDE QUARTER <i>(feet)</i>	INSIDE QUARTER <i>(feet)</i>	INSIDE QUARTER <i>(feet)</i>	OUTSIDE QUARTER <i>(feet)</i>
Cut-J Sta. 0+00 - 67+00.02	Apr-16	400	1.3	34	33.9	34.5	34.4	33.9
Cut-J Widener	Apr-16	Varies		34	34.0			
Cut-J2 Sta. 0+00 - 58+87.86	Apr-16	400	1.1	34	35.6	36.9	36.4	35.7
Cut-K Sta. 0+00 - 150+00	Apr-16	400	2.8	34	34.0	34.7	35.6	34.5
Cut-K Widener Sta. 120+00 - 150+00	Apr-16	Varies	0.6	34	34.6			

REMARKS *(Continue on reverse)*  
Survey 14-066