

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(EP 1130-2-520)

PAGE: 1 OF 1

DATE: 23-Jan-17

TO:
 Chairman, Board of County Commissioners
 Sarasota, Fl.

FROM:
 USACE, District Engineer
 Attn: CESAJ-OD-H Jacksonville, Florida

New Pass, Sarasota County, Florida

MINIMUM DEPTHS IN CHANNEL
 ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Cut-1 Sta. 0+00 to 28+33.68	Jan-17	150	0.54	10	10	7.9	2.8
Cut-2 Sta. 0+00 to Sta. 16+46.96	Jan-17	150-125	0.31	10	3	2.3	4.4
Cut-3 Sta. 0+00 to Sta. 16+90.58	Jan-17	125-100	0.32	8	9.4	10.1	9.5
Cut-4 Sta. 0+00 to Cut 7 Sta. 19+96.81	Jan-17	100	0.38	8	6.9	7.7	9.1
Cut-5 Sta. 0+00 to Sta.23+42.07	Jan-17	100	0.44	8	8.9	8.2	8.4
Cut-6 Sta. 0+00 to Sta. 39+30.60	Jan-17	100	0.74	8	4.2	4.4	4.4
Cut-7 Sta. 0+00 to Sta. 35+21.93	Jan-17	100	0.67	8	8.3	8.8	9.2
Turning Basin: Sta. 0+00 to Sta. 8+00	Jan-17	Varies	0.15	8	7.5	5.0	3.6

REMARKS(Continue on reverse)

Survey #17-033