


Site Photographs




Photo 1 – Dense exotic vegetation and scattered native ground cover present.



Photo 2 – Dense exotic vegetation found throughout.








RS Environmental Consulting Inc. P.O. Box 161158 Miami FL, 33116 Phone: 305-383-3404 www.rs-env.com Location Map T-52S, R-40E, S-9 T-52S, R-40E, S-16

DRAWN BY: LVK
CHECKED BY: RWS

DATE: 10/25/2016

RWS SCALE: As Shown






RS Environmental Consulting Inc. P.O. Box 161158 Miami FL, 33116 Phone: 305-383-3404 www.rs-env.com Soils Map T-52S, R-40E, S-9 T-52S, R-40E, S-16

DRAWN BY: LVK
CHECKED BY: RWS

DATE: 10/25/2016 SCALE: As Shown






RS Environmental Consulting Inc. P.O. Box 161158 Miami FL, 33116 Phone: 305-383-3404 www.rs-env.com v

Wetland ID Map T-52S, R-40E, S-9 T-52S, R-40E, S-16

DRAWN BY: LVK
CHECKED BY: RWS

DATE: 10/25/2016 SCALE: As Shown





RS Environmental Consulting Inc. P.O. Box 161158 Miami FL, 33116 Phone: 305-383-3404 www.rs-env.com Secondary Impacts Map T-52S, R-40E, S-9 T-52S, R-40E, S-16

DRAWN BY: LVK

DATE: 10/25/2016 SCALE: As Shown

CHECKED BY: RWS