

Figure 4-13 Simulated and Observed Groundwater Table and Monthly Rainfall and Simulated Actual Evapotranspiration at OS-181.