

**REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 400 FEET WIDE OR GREATER**

(ER 1130-2-316)

PAGE: 1 of 1

DATE: Jan-13

TO: CESAJ-OD Brian Brodehl

FROM: CESAJ-OD Deb Williams
Lisa Holland

THRU: CESAJ-OD Dale Traylor

Tampa Harbor, Upper Hillsborough Bay, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Upper Sparkman Channel: from green Daybeacon-5 to Junction with Ybor Channel	Jan-13	400	0.7	34	34.0	36.5	33.2	33.1
Ybor Channel	Jan-13	400	0.8	34	22.4	23.1	27.8	27.8
Garrison Channel (deauthorized)	Jan-13	275-1945	0.4	34	25.5	25.5	29.2	31.8

REMARKS(Continue on reverse)

Survey #13-028, Dated January 2013