

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 400 FEET WIDE OR GREATER
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: 3-Sep-2015

TO:
Commander, Naval Submarine Base, Kings Bay
Attn.: Code FE21, GA.

FROM:
USACE, District Engineer
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE
Kings Bay Entrance Channel, GA

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Cut-1N Sta. 350+00 - 501+24	Jul-15	500	2.86	48	48.4	48.7	47.2	40.7
Cut-1N Sta. 200+00 - 350+00	Jul-15	500	2.84	46	45.8	47.6	47.4	43.1
Cut-1N Sta. 71+00 - 200+00	Jul-15	500	2.44	46	47.4	47.8	46.5	39.8
Cut-1N Sta. 0+00 - 71+00 Widener	Jul-15	500	1.34	46	44.0	43.9	48.2	48.0
Cut-1N North Turning Basin Sta. 11+00 - 71+00	Jul-15	350	1.14	46	45.3	45.0	45.3	45.1
Cut-1N South Turning Basin Sta. 11+00 - 71+00	Jul-15	350	1.14	46	39.9	38.6	39.7	42.4

REMARKS(Continue on reverse)
Survey #15-162