

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 100 FEET WIDE OR GREATER
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: March 30, 2016

TO:
Executive Director, Florida Inland Navigation District
1314 Marcinski Road, Jupiter, Florida

FROM:
USACE, District Engineer
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE
Intracoastal Waterway, Matanzas Inlet Area, St. Johns County, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Cut-SJ-59 Sta. 0+00 to 23+83.83 Widener	Feb-16	125	0.45	12	9.8	12.1	13.0	13.8
					10.4	14.1		
Cut-SJ-60 Sta. 0+00 to 26+86.34 Widener	Feb-16	125	0.51	12	2.7	2.3	2.8	3.6
					4.3	10.5		
Cut-SJ-61 Sta. 0+00 to 15+00.00 Widener	Feb-16	125	0.28	12	4.0	3.8	2.6	2.5
					5.7			

REMARKS(Continue on reverse)

Survey #16-050