

TO: Chairman, Port, Waterway and Beach Commission, St. Augustine, FL	FROM: USACE, District Engineer Attn: CESAJ-CO-OM Jacksonville, Florida
---	---

RIVER/HARBOR NAME AND STATE St. Augustine Harbor, St. Johns Co., FL	MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	Date of Survey	AUTHORIZED PROJECT			Left Outside Quarter (feet)	Middle Half (feet)	Right Outside Quarter (feet)
		Width (feet)	Length (miles)	Depth (feet)			
St. Augustine Inlet: from opposite green Can Buoy-3 to opposite Red Nun Buoy-4	May-2003	200	0.5	16	19.1 (1)	16.6 (1)	15.1 (1)
From opposite red Nun Buoy-4 to opposite green lighted Buoy-7	May-2003	200	0.7	16	18.1 (1)	18.9 (1)	15.7 (1)
From opposite green lighted Buoy-7 to the intersection of the Intracoastal Waterway at red Nun Buoy-6.	May-2003	200	0.8	16	23.7 (1)	25.3 (1)	17.3 (1)

Remarks:

1. This report is based on the channel as marked by the U.S. Coast Guard with floating buoys. This is a natural channel, located outside of the current defined Federal channel limits in some areas, which may provide adequate navigation of the inlet.