






Path: P:\GIS_Projects\EJ\2013\472\00\fig\ACOE\Conceptual\HRM Location.mxd Date: 11/10/2016 1:50:02 PM
















Path: P:\GIS_Projects\EJ\2013\472\00\fig\ACOE\Conceptual\HRD PSC.mxd Date: 11/9/2016 5:30:20 PM





































Path: P:\GIS_Projects\EJ\2013\472\00\fig\ACOE\Conceptual\HRD PSC.mxd Date: 11/9/2016 5:30:20 PM


































































PERMIT NO. SAJ-2006-1838 (SP-TSB)

Impact

Jurisdictional Wetland Impacts - 17.07 ac. Non-Jurisdictional Ditch Impact - 5.505 ac. **Mitigation** Upland Preservation - 20.17 ac. Wetland Preservation - 63.21 ac.

HUNTINGTON WOODS













Image: system of the	 Project Boundary Ditch Lakes < 10 ac. Borrow Areas Spoil Areas Trail Roads 	Mitigation Upland Enhancement (193.90 ac.±) Upland Preservation (2.73 ac.±) Wetland Enhancement (1,675.47 ac.±)	8A 8B 8C 8D 8E 8F 8G 8H 8I 8J 8K 8L 8M 8N 8O 8P 8Q 8R 8M 8N 8O 8P 8Q 8R 8S 8T 8U 8V 8W 8X 8Y 8Z 8AA 8BB 8CC 8D 8EE 8FF 8GG 8HH 8II 8JJ 8KK 8LL 8MM 8NN 8OO 8PP 8QO 8RR 8SS 8TT 8UU 8WW 8WW 8XX
ENVIRONMENTAL SERVICES, INC. 720 Financial Way, Suite 100 Jacksonville, Florida 32256 (904) 470-2200 (904) 470-2112 Fax www.environmentalservicesinc.com	H	Site Conditions - Mitigation Site unter's Ridge agler County, Florida	Project:EJ13472.00Date:Nov 2016Drawn By:JRNChecked By:LSKApproved By:JLBFigure: 8A



















Image: system of the	 Project Boundary Ditch Lakes < 10 ac. Borrow Areas Spoil Areas Trail Roads 	Mitigation Upland Enhancement (193.90 ac.±) Upland Preservation (2.73 ac.±) Wetland Enhancement (1,675.47 ac.±)	8A 8B 8C 8D 8E 8F 8G 8H 8I 8J 8K 8L 8M 8N 8O 8P 8O 8R 8M 8N 8O 8P 8O 8R 8S 8T 8U 8V 8W 8X 8Y 8Z 8AA 8BB 8CC 8DD 8EE 8FF 8GG 8HH 8II 8JJ 8KK 8LL 8MM 8NN 8OO 8PP 8QO 8RR 8SS 8TT 8UU 8VV 8WW 8XX
ENVIRONMENTAL SERVICES, INC. 7220 Financial Way, Suite 100 Jacksonville, Florida 32256 (904) 470-2200 (904) 470-2112 Fax www.environmentalservicesinc.com	H	Site Conditions - Mitigation Site unter's Ridge agler County, Florida	Project:EJ13472.00Date:Nov 2016Drawn By:JRNChecked By:LSKApproved By:JLBFigure:8H




















































\bigcirc					\square
				1D	
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	D.	
	1				
Disclaimer: The information conceptual purposes only, se	erves to aid a licensed engineer or sional services, and is subject to	 Project Boundary Ditch Lakes < 10 ac. Borrow Areas Spoil Areas Trail Roads 	Mitigation Upland Enhancement Upland Preservation (2 Wetland Enhancement	2.73 ac.±)	8A 8B 8C 8D 8E 8F 8G 8H 8I 8J 8K 8L 8M 8N 8O 8P 8O 8R 8M 8N 8O 8P 8O 8R 8S 8T 8U 8V 8W 8X 8Y 8Z 8AA 8BB 8CC 8D 8EE 8FF 9GG 8HH 8II 8JJ 8KK 8LL 8MM 8NN 8OO 8PP 8QO 8RR 8SS 8T 8UU 8VV 8VW 8XX
SE 722 3ack (904 (904	NVIRONMENTAL CRVICES, INC. D Financial Way, Suite 100 (sonville, Florida 32256) 470-2200 0) 470-2112 Fax entalservicesinc.com	н	Site Conditions - Mitigation unter's Ridge lagler County, Florida	Site	Project:EJ13472.00Date:Nov 2016Drawn By:JRNChecked By:LSKApproved By:JLBFigure:82
















Path: P:\GIS_Projects\EJ\2013\472\00\fig\ACOE\Conceptual\HRM PSC.mxd Date: 11/16/2016 9:04:17 PM





















































Path: P:\GIS_Projects\EJ\2013\472\00\fig\ACOE\Conceptual\HRM PSC.mxd Date: 11/16/2016 9:04:17 PM