

**REPORT OF CHANNEL CONDITIONS  
100 TO 400 FEET WIDE**  
*(EP 1130-2-520)*

PAGE: 1 OF 1

DATE: Jun-13

TO: CESAJ-OD Brian Brodehl

FROM: Jeff Ware  
Lisa Holland

THRU: CESAJ-OD Dale Traylor

RIVER / HARBOR NAME AND STATE

MINIMUM DEPTHS IN CHANNEL  
ENTERING FROM SEAWARD

Fort Myers Beach Harbor, Lee County, FL

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Entrance Channel: San Carlos Bay from 1,400 feet seaward of green Light-1 to green Light-9	Jun-13	150-325	1	12	11.3	12.0	10.3
Cut 3: From green Light-9 to 250 feet south of green Daybeacon-13	Jun-13	125-325	0.4	12	9.6	9.4	11.0
Cut-4 thru Cut-6: From 250 feet south of green Daybeacon-13 to State Road 865 Bridge	Jun-13	125-195	0.6	12	10.8	11.1	10.3
Inner Channel, Cut-6 thru Cut-8 (Matanzas Pass): From State Road 865 Bridge to red Daybeacon-24	Jun-13	125-260	0.3	11	6.9	8.3	7.9
Cut-9 thru Cut-10: From red Daybeacon-24 to 350 feet west of red Daybeacon-28	Jun-13	125	0.3	11	10.4	8.8	8.0
Turning Basin	Jun-13	125-275	0.1	11	8.2	7.2	6.3

Remarks:  
Survey # 13-044