

**REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 200 FEET WIDE OR GREATER**

*(ER 1130-2-316)*

PAGE: 1 of 1

DATE: March 12, 2014

TO:  
Chairman, Port, Waterway and Beach  
Commission, St. Augustine, Florida

FROM:  
USACE, District Engineer  
CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE  
St. Augustine Harbor, St. Johns County, Florida

MINIMUM DEPTHS IN EACH 1/3  
WIDTH OF CHANNEL  
ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE (feet)	MIDDLE INSIDE (feet)	RIGHT OUTSIDE (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Entrance Channel Sta. 0+00 to 40+00	Mar-14	200	0.76	16	14.4	12.7	13.6
Entrance Channel Sta. 40+00 to 80+00	Mar-14	200	0.76	16	13.7	14.8	16.0
Entrance Channel Sta. 80+00 to 124+00.29	Mar-14	200	0.83	16	16.9	12.5	6.8

REMARKS *(Continue on reverse)*  
**Survey #14-053**