

REPORT OF CHANNEL CONDITIONS  
FOR CHANNELS 75 FEET WIDE OR GREATER  
(ER 1130-2-316)

PAGE: 1 of 1

DATE: Dec-14

TO:  
Dixie County Board of Commissioners  
Cross City, Florida

FROM:  
USACE, District Engineer  
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE  
Horseshoe Cove, Dixie County, Florida

MINIMUM DEPTHS IN EACH 1/4  
WIDTH OF CHANNEL  
ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE (feet)	MIDDLE INSIDE (feet)	RIGHT OUTSIDE (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Entrance Channel Sta. 100+00 - Sta. 152+80	Aug-14	75	1.0	6	5.2	5.9	5.7
Entrance Channel Sta. 152+80 - Sta. 181+35	Aug-14	75	0.54	6	3.3	3.7	3.3
Turning Basin Sta. 181+35 - Sta. 188+36.35	Aug-14	75	0.13	6	2.2	3.5	3.6

REMARKS(Continue on reverse)

Survey #14-112