

REPORT OF CHANNEL CONDITIONS FOR CHANNELS 300 FEET WIDE OR GREATER (ER 1130-2-316)						PAGE: 1 of 1 DATE: November 13, 2014		
TO: Chairman Board of County Commissioners P.O. Box 398 Fort Myers, Florida					FROM: USACE, District Engineer Attn.: CESAJ-ODH Jacksonville, Florida			
RIVER/HARBOR NAME AND STATE Boca Grande Pass, Lee County, Florida					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD			
CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Outer Cut Sta. 0+00 - Sta. 54+27.04	Oct-14	300	1.03	32	8.4	9.7	9.7	9.6
Outer Cut Sta. 54+27.04 - Sta. 108+54.08	Oct-14	300	1.03	32	12.4	12.9	13.2	17.4
Inner Cut Sta. 108+54.08 - Sta. 161+34.08	Oct-14	300	1.0	32	6.5	8.0	8.2	10.4
Inner Cut Sta. 161+34.08 - Sta. 214+14.08	Oct-14	300	1.0	32	34.2	32.2	32.0	31.4
Inner Cut Sta. 214+14.08 - Sta. 250+00.18	Oct-14	300	0.68	32	38.9	40.2	41.9	39.8
REMARKS(Continue on reverse) Survey #14-116								