

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 400 FEET WIDE OR GREATER
(ER 1130-2-316)

PAGE: 1 OF 1

DATE: March 27, 2015

TO:
Blount Island Command
5880 Channel View Boulevard, Jacksonville, Florida 32226-3404

FROM:
USACE, District Engineer
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE: Blount Island Marine Terminal, Florida

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)				
Entrance Channel Sta. 35+00 - 56+09.10	Mar-15	415	0.40	38	34.3	36.5	36.1	33.2
Entrance Channel Sta. 12+00 - 35+00	Mar-15	415	0.43	38	33.8	37.5	37.2	34.1
Berths 1 and 2 Sta. 0+00 - 12+00	Mar-15	572	0.23	38	28.6	32.0	31.6	23.6

REMARKS(Continue on reverse)
Survey 15-046