

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 50 FEET WIDE OR GREATER
(ER 1130-2-316)

Page:
1 OF 1
Date:
November 30, 2016

TO:
Chairman, Board of County Commissioners
Perry, Taylor County, Florida

FROM:
USACE, District Engineer
Attn: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE
Cedar Island / Keaton Beach, Florida

MINIMUM DEPTHS IN EACH WIDTH OF
CHANNEL ENTERING FROM SEAWARD

| NAME OF CHANNEL | DATE OF SURVEY | AUTHORIZED PROJECT | | | OUTSIDE QUARTER (feet) | INSIDE HALF (feet) | OUTSIDE QUARTER (feet) |
|--------------------------|----------------|--------------------|-------------------|-----------------|---------------------------|-----------------------|---------------------------|
| | | WIDTH (feet) | LENGTH (miles) | DEPTH (feet) | | | |
| Cut-1 0+00 - 4+63.48 | Nov-16 | Varies | 0.09 | 4 | 4.4 | 4.8 | 4.4 |
| Cut-2 0+00 - 6+90.86 | Nov-16 | 50 | 0.13 | 4 | 4.4 | 3.8 | 4.0 |
| Cut-3 0+00 - 6+99.00 | Nov-16 | 50 | 0.13 | 4 | 1.8 | 1.4 | 2.0 |
| Cut-4 0+00 - 4+93.71 | Nov-16 | 50 | 0.09 | 4 | 4.3 | 3.4 | 3.4 |
| Cut-5 0+00 - 11+35.67 | Nov-16 | 50 | 0.22 | 4 | 4.4 | 4.7 | 4.5 |
| Cut-6 0+00 - 10+06.78 | Nov-16 | 50 | 0.19 | 4 | 5.9 | 5.7 | 5.5 |
| Cut-7 0+00 - 20+15.20 | Nov-16 | 50 | 0.38 | 4 | 4.6 | 5.1 | 5.3 |
| Cut-8 0+00 - 20+65.23 | Nov-16 | 50 | 0.39 | 4 | 5.1 | 4.7 | 4.5 |
| Cut-9 0+00 - 39+77.57 | Nov-16 | 50 | 0.75 | 4 | 2.6 | 2.6 | 2.9 |

REMARKS(Continue on reverse)
Survey #16-196