

REPORT OF CHANNEL CONDITIONS
FOR CHANNELS 75 FEET WIDE OR GREATER
(ER 1130-2-316)

PAGE: 1 of 1

DATE: 23 Nov. 2016

TO:
Dixie County Board of Commissioners
Cross City, Florida

FROM:
USACE, District Engineer
Attn.: CESAJ-ODH Jacksonville, Florida

RIVER/HARBOR NAME AND STATE
Horseshoe Cove, Dixie County, Florida

MINIMUM DEPTHS IN EACH 1/4
WIDTH OF CHANNEL
ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE (feet)	MIDDLE INSIDE (feet)	RIGHT OUTSIDE (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Entrance Channel Sta. 100+00 - Sta. 152+80	15-16 Nov. 2016	75	1.0	6	3.9	4.2	4.3
Entrance Channel Sta. 152+80 - Sta. 181+35	15-16 Nov. 2016	75	0.54	6	2.6	2.9	2.4
Turning Basin Sta. 181+35 - Sta. 188+36.35	15-16 Nov. 2016	75	0.13	6	2.6	2.9	2.4
Turning Basin West One	15-16 Nov. 2016	Varies	Varies	6	2.5		
Turning Basin West Two	15-16 Nov. 2016	Varies	Varies	6	2.1		
Turning Basin West Three	15-16 Nov. 2016	Varies	Varies	6	2.1		
Turning Basin East	15-16 Nov. 2016	Varies	Varies	6	2.0		

REMARKS(Continue on reverse)

Survey #17-028